


TRUSS ASS'Y ELEV
MODIFIED WARREN PONY TRUSS



$\frac{1}{4}'' = 1'$

EGLT

TOM & GINNIE HOWARD BRIDGE



SUGGESTED DESIGN SK-1.1 SUPERCEDES SK-1

SK-1.1




JMC 11/30/22

NOTES:

1. ALL LUMBER PRESSURE TREATED FOR OUTDOOR USE.
2. UPPER CHORD 2x8, LOWER CHORD 2x10 LUMBER.
3. 30" SPLICE AT INDICATED JOINTS.
4. ALL WEB MEMBERS AND KNEE BRACE 2x6 LUMBER.
5. END PL AND DECK CROSS BEAMS 2x10 LUMBER.
6. DECK STRINGER 2x6 LUMBER.



1/2" = 1'



DETAIL "B" 1/2" = 1'

DETAIL "A" 1" = 1'

EGLT
TOM & GINNIE HOWARD BRIDGE
SUGGESTED FOOTING

SK-2

JUNE 11:30:22

Map Find Data Coordinates Draw Print/EExport/Status
Home Full Screen Satellite View Print Back Home Layer List



- Layers
- Connecticut
 - Towns
 - Boundaries
 - Built Environment
 - Contours 2016
 - Watersheds
 - Bioclimes
 - Water Resources
 - Open Space
 - Coastal Resource Management
 - Water Quality Classifications
 - Water Quality
 - Soils
 - Geology
 - Statewide Imagery
 - Regional Imagery
 - Coastal Imagery
 - Elevation
 - Hillshade
 - ShadedRelief
 - Aspect
 - Slope
 - Elevation





Amanda Thompson

President, East Granby Land Trust

PO Box 39

East Granby, CT 06026

12/4/2022

Dear Amanda,

On December 2, 2022 I performed an onsite investigation of the soils at the site of the proposed wooden walking bridge on the Howard Preserve. The crossing site consists of a transect from an upland area dominated by sloping non-wetland soils formed in sand and gravel deposits, that then crosses a wet side channel of an unnamed tributary, and then floodplain soils on the edge of the agricultural field dominated by floodplain soils. I examined the soils in greater detail than shown in the USDA NRCS Soil Survey. I offer the following additional information on the soils in the crossing from East to West:

- 1- Wooded Sloping area and streambank, eastern side- Excessively drained non wetland Hinkley soils, with a narrow band (approx. 3ft in width) of moderately well drained Sudbury soils are on the streambank adjacent to the channel, and may flood rarely. A blue flag was placed on the upslope side.
- 2- Side Channel- This channel of an intermittent water course is dominated by very poorly drained soils formed in alluvium. It also appears to capture some groundwater seepage from upslope areas. Similar soil series would be Saco soils.
- 3- Wooded bank on western side- Dominated by somewhat poorly drained soils formed in very fine sandy loam alluvium. These unnamed soils are slightly wetter than the similar Pootatuck soils.

The proposed crossing is on the back side of the floodplain, and includes crossing a shallow mucky woody debris filled channel associated with an intermittent watercourse. There was no evidence of significant scour, and finer textured soils would indicate there is low energy from any flooding events. Below is a picture of the crossing area, with the blue flag barely visible to the east in the center of the picture.



Should you have additional questions, please feel free to contact me.

Sincerely,

Kip

Kipen J. Kolesinskas

Consulting Conservation Scientist

Professional Soil Scientist

860-878-0393